Work Order ID 63793

Monday, November 15, 2010 8:30:03 AM



Page 1

Item ID:

D206-642-247

Accept

Setup Start

Stop



Revision ID:

Item Name:

Wearshoe

Start Date:

11/12/2010 **Required Date:** 11/19/2010

Start Qty: 1.00

Req'd Qty: 1.00

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

QC:

Date:

Date: 10-11-15 Tooling:

SPC (Y/N):

Date:

Date:

Start Run

Stop

Sequence ID/ Work Center ID

Operation Description

Revision Nbr

Set Up/ **Run Hours** **Tool ID**

Tool # Plan Code

Reject Accept **Qty**

Qty

Reject Number

Insp. Stamp

Draw Nbr

DSI 9466 Rev A Rev N

IIN D206-642

0.00

Document Control

Memo

0.00

Photocopy bluefile and create labels per PPP D206-642-247

CHG002

D (30/11/30)

110

100

Packaging Packaging

Pick Kit

0.00

Memo

0.00

BG 10-11-16

Dail Aciospace Liu	Dart	Aeros	pace	Ltd
--------------------	------	--------------	------	-----

W/O:			WC	ORK ORDER CHANG	ES				
DATE	STEP	PRC	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								, rou mgr	
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A:	_ Date: _	
	R	esolution:	Dispositio	n:	_ QA: N/C C	losed:		Date: _	
NCR:		1	WORK ORD	ER NON-CONFORMA	ANCE (NCI	7)			
		Description of NC	Corrective Action Section		Verifi	cation	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	ion C	Chief Eng	QC Inspector
					į.				
					į				
l									

Monday, November 15, 2010 8:30:03 AM

Item ID:

D206-642-247

Accept

Setup Start

Stop



Revision ID:

Item Name: Wearshoe

Required Date: 11/19/2010

Start Date:

11/12/2010

Start Qty: 1.00

Req'd Qty: 1.00



Date:

Cust Item ID: Customer:

Tool ID

Reference:

Approvals:

QC:

Process Plan:

Date: _______

Tooling:

SPC (Y/N):

Date: Date:

Run Start

Stop



Sequence ID/ Work Center ID

120

Quality Control

Operation Description

QC4- 100% Inspect kits for completeness

Memo

Memo

Set Up/ **Run Hours**

0.00

8 014/30

Tool # Plan Code

Accept Qty

Reject Qty

Reject Insp. Number Stamp

130

Packaging

Packaging

fros

Identify and pack for shipping as per PPP D206-642-247

140

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/12/0190 Bf10-12-1

Dart Ae	rospace	Ltd								•
N/O:			V	VORK ORDER CH	ANGES					
DATE	STEP	PRO	OCEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Category:			R: Yes	No DQ	A:	_ Date: _	
	Re	solution:	Disposition: (QA: N/C Closed: Da				
NCR:			WORK OR	DER NON-CONFO	RMANCE	(NCR)			
DATE	STEP	Description of NC		Corrective Action	Section B	0:	- Verifi	cation	Approvai	Approvai
	0111	Section A	Initial Chief Eng	Action Descrip	otion	Sign & Date	Sect	ion C	Chief Eng	QC Inspecto
						Į·.,				

Picklist Print

Monday, November 15, 2010 8:30:07 AM

Work Order ID: 63793

Parent Item: D206-642-247

Parent Item Name: V. earshoe



Elart Date: 11/12/2010

Required Date: 11/19/2010

Start Qty: 1.00

Required Qty: 1.00

	Comments:	New Issue Aug. 23	3/2010 DL					ì						
	Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
_	AN960C10L	NAS1149C0332 R	Purchased	No			110	Each	25.0000	44	44			1
>	washer	AL HAN ENNAN ALTAK									M115	83212) ₁₁ /	95/
					Location	<u>!</u>	Loc	<u>Oty</u>	Loc Code					,
					ST245	107534		25 25		_		_	1	
/	D3535-13		Manufactured	No		107554	110	Each	3.0000	1	1		//	
>	Wearshoe										101	/ ₁₁ / ₁₉₈₀		
	W carsinoe				<u>Location</u>	<u>1</u>	Loc	<u>Qty</u>	Loc Code					
,					FP018			3		_	,	_		
	D3535-21		Manufactured	No	<u>_</u>	62006	110	3 Each	5.0000	1	1		Λ	
>			Manufactured	110			110	Lucii	3.0000		181	1/194	/	
	Wearshoe				Location	1	Loc	Otv	Loc Code			· /		
					FP	-		5				_		
	D2525.22					55730		5		_		_	1	
/ 0	D3535-33		Manufactured	No			110	Each	8.0000		101	11951		\
	Wearshoe				Location	n	Loc	Otv	Loc Code			/		
					FP19	-	200	8						
						61502		8	1	-		- -		

Dart Aerospace Ltd

W/O:			WO	RK ORDER CHANG	SES					
DATE	STEP	PRO	E	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
Part No) :	PAR #:	Fault Categ	jory:	NCR:	Yes I	No DQ	A :	Date:	
	R	esolution:	Disposition	:	QA: N	/C Clo	sed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCR				
	1	Description of NC		tion B	Verific	ation	Approval	Approval		
DATE	STEP	STEP Description of NC Section A	Initial Chief Eng	Action Description Chief Eng		ign & Date	Secti		Chief Eng	QC Inspector
							•			
}										
1	}						1		{	

Monday, November 15, 2010 8:30:07 AM

Shop Packet Print

Loc Qty

46

37

Loc Code

Location

62661 63313

FP017

Page 2

Dart Aerospace Ltd

	р									4	
W/O:			WO	RK ORDER CH	ANGES						
DATE	STEP	PRO	CEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
				•							
Part No: PAR		PAR #:	Fault Categ	NC	NCR: Yes No DQA: Date:						
Resolution:			Disposition	n:	QA	N/C CI	sed:		Date: _	<u> </u>	
NCR:		\	WORK ORDE	R NON-CONFO	PRMANCE	(NCR)				
DATE	STED	STEP Description of NC Section A		Section B	0. 0	Verific	cation	Approval	Approval		
DAIL	JILF		Initial Chief Eng	Action Descrip Chief Eng	otion	Sign & Date	Secti	on C	Chief Eng	QC Inspecto	
								,			
										i	
					1. · · · · · · · · · · · · · · · · · · ·						

Monday, November 15, 2010 8.30:08 AM

Work Order ID: 63793

Parent Item:

D3537-3

D206-642-247

Parent Item Name: Wearshoe



Start Date: 11/12/2010

Required Date: 11/19/2010

Start Qty: 1.00

Required Qty: 1.00

Wearpad

110

Each

26.0000

MS27039C1-08

Purchased

Manufactured

No

Location Loc Qty FP17 26 61674 62705 20 110

Each 715.0000

- } {###################################	
SCREW	

Location	Loc Qty
FP	63
115336	63
ST293	652
115589	391
116022	260
19185	1

Loc Code

Loc Code

Dart Ae	rospace	Ltd							. ≺
W/O:			W	ORK ORDER CHANGE	S				•
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						-1010			
Dort No.	-	DAD #	F 11 O . 1		NOD V	N			
Part No	·	PAR #:	Fault Cat	NCH: Yes	No DQ	A:	_ Date: _		
	R	esolution:	Dispositi	QA: N/C C	Date: _				
NCR:		V	VORK ORE	DER NON-CONFORMAI	NCE (NCF	R)			
DATE	OTED	Description of NC		Corrective Action Section		Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sect	ion C	Chief Eng	QC Inspector
					,				
		·							
									1

DART AEROSPACE USA, INC.



D206-642 Page 21 of 34

206A/B HIGH GEAR SKIDTUBES 4.3

							m. Address	Description
Item	Qty	Qty	Qty	Qty	Qty	Qty	Part Number	Description
	-211	-212	-213	-214	-241	-247	D000 040 044	PVIDTURE INSTALL ATION ! H
	X						D206-642-211	SKIDTUBE INSTALLATION, LH
		X					D206-642-212	SKIDTUBE INSTALLATION, RH SKIDTUBE INSTALLATION, LH, THRU BOLT
			X				D206-642-213	SKIDTUBE INSTALLATION, CH, THRU BOLT
				X			D206-642-214	
	1	1	1	11	Х		D206-642-241	SKIDTUBE
						X	D206-642-247	WEARSHOE KIT (REPLACES -243)
	1	1	1	1			D206-651-041	* 206 GHW ADAPTER (3)
					1		D2650-3	SKIDTUBE ASSEMBLY
1					18		D2650-3	* PLUG (1)
2A					18		D2651-3	* O-RING (1)
2B					1		D2646	* AFT CAP (1)
3 .					2		M\$27039-1-08	*SCREW (1)
4					2		AN960JD10L	* WASHER (1)
5							MINAGOSOTOL	WAGITER
6	1		1				D2665-1	SADDLE, FWD OUT, LH
6		1		1			D2665-2	SADDLE, FWD OUT, RH
7	1		1				D2666-1	SADDLE, FWD IN, LH
7		1		1			D2666-2	SADDLE, FWD IN, RH
8	1	<u> </u>			•		D2665-1	SADDLE, AFT OUT, LH
8	-	1					D2665-2	SADDLE, AFT OUT, RH
8		L	1				D2667-1	SADDLE, AFT OUT, LH
8				1			D2667-2	SADDLE, AFT OUT RH
9	1						D2666-1	SADDLE, AFT IN, LH
9		1					D2666-2	SADDLE, AFT IN, RH
9			1			-	D2668-1	SADDLE, AFT IN, LH
9			<u> </u>	1			D2668-2	SADDLE, AFT IN, RH
10	8	8	8	8			AN3-41A	BOLT
11	16	16	16	16			D2652	BUSHING
12A	8	8	8	8			MS21042-3	NUT (OR MS21042L3)
12B	8	8	8	8			AN960JD10	WASHER
13	4	4	4	4			AN5-7A	BOLT
14	4	4	4	4			AN5-11A	BOLT
14A			2	2			AN5-32A	* BOLT (2)
14B			2	2			MS21042-5	* NUT (OR MS21042L5) (2)
15	8	8	8	8			AN960JD516	WASHER
16	12	12	12	12			AN4-6A	BOLT
17	24	24	24	24			AN960JD416	WASHER
18	12	12	12	12			MS21042-4	NUT (OR MS21042L4)
								LUISADDAD (DEDLACEC DOCAR 2)
20A					4	. 4	D3537-1	WEARPAD (REPLACES D2648-3)
21A					1	1	D3537-3	WEARPAD (REPLACES D3429-1) WEARSHOE (REPLACES D2656-13)
22A		ļ	ļ		1	1 1	D3535-13	-GASKET
22B			··· <u>ч</u>		1		D3535-13	WEARSHOE (REPLACES D2656-21)
23A	ļ				1	7.1	D3536-21	GASKET
23B	<u> </u>					1 1	D3535-21	WEARSHOE (REPLACES D2656-33)
24A		L			1	1	D3535-33 D3536-33	GASKET D2030-00)
24B	L	 	 		44	.44	MS27039C1-08	SCREW
26A			 	ļ	44	44	AN960C10L	WASHER
26B		ļ			44	+44	ALS7-1032-130	* INSERT (1)
26C					44		AL37-1032-130	(or AKS4-1032-130, ALS4-1032-130, AELS-1032-130)
28	2	2	2	2	<u> </u>		AN6-44A	BOLT
29A	2	2	2	2			MS21042-6	NUT (OR MS21042L6)
29B	4	4	4	4			AN960JD616	WASHER
34	1	1	1	1			AN4C5A	BOLT
35	1	1 1	1	1	· · · · ·		AN960C416	WASHER
36	1	1	1	1	†		D3413-1	RING (REPLACES D2655)
								or consu
37	10	10	5	5			D2712	SET SCREW
38	2	2	2	2			D2884	SADDLE SPACER
39	2	2	2	2	L		D2885	SADDLE SPACER

NOTES: (1) DENOTES THAT PART IS INCLUDED WITH D2650-3 ASSEMBLY ABOVE
(2) MAY BE REQUIRED ON -213/-214 INSTALLATIONS
(3) NOT INSTALLED AS PART OF SKIDTUBE. USED TO MODIFY OEM GROUND HANDLING WHEELS

COPYRIGHT © 2000 BY DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

Revision:

09.09.09 Date: